

SOLID LEASABLE MINERAL SYSTEM
(SLS)
INSPECTION RECORD

1-19-88

Mine Name (E135): Haystack Exploration Tract - Date of Inspection: August 5, 1987
 Lessee (E24): Todilto Exploration Lessor: _____
 Inspector(s): Jay Smith, BLM. Company Representative(s): None
Roger Baer, BLM

Inspection Type: Mining Related ☐ / Exploration Related ☒ / Inactive Tract ☐ /
 (check one) (FY86 E105) (FY86 E107) (FY86 E109)

Serial No. (E1)	Holder of Primary Tract Interest (E24)	Tract Type (E11)	Commodity (E9)	Inspection Time (E106, E108, E110)
NOO-C-14-20 5681	Same as above	lease	Uranium	2.4
8396	Same as above	lease	Uranium	2.4

Inspection Time: Preparation Time: 0.5
 (calculation) Travel Time (both ways): 2.0
 Onsite Time: 2.0
 Reporting Time: 0.2
 Clerical: 0.1
 TOTAL: 4.8
 (E106, E108, E110)

NOTE: If more than one tract is inspected on the same trip, the inspection should be prorated to all tracts inspected on a percentage basis. Show proration calculation on back. Example: Tract A and Tract B take 10 hours to inspect, but 75% of the inspection was on Tract A. Inspection time for Tract A is (75% of 10 hrs.) 7.5 hours and Tract B is 2.5 hours.

Was a condition of noncompliance encountered? Yes _____ No X
 Was an undesirable event encountered? Yes _____ No X

NOTE: If "Yes" to either of the above, prepare the appropriate report.

Purpose of Inspection: To determine general condition of lease area. Found declines had both reopened - located within 100 yards, where family lives.

cc: Area Director, NAO
 Supertinent, ENA
 Lease file